TB01-2023

Technical Bulletin

Firmware 2.0.12.11 Maintenance Release

This bulletin is to notify the user of all Flux Power battery models that a firmware update on specified batteries.

Batteries Affected

All of the following models: S8, S24, M24, M36, C24, C48, L48 and X48. You can find this models name on the battery's I.D. plate which is typically located on the top, or front of the battery, and for some models an additional label on the back of the battery.

Identifying the Issue

We have identified enhancements to all UL and Non-UL listed battery firmware versions prior to 2.0.12.11:

	Issue	Description
a)	CAN Node drop.	For BDI packs, you would see DTC 6,11,12 & 23. For 6 LED
		internal SOC packs, you can observe DTC 3 flashing. Pack wont
		charge or energize its ports.
b)	SOC drop & Over-Discharge	For BDI packs, you would see DTC 6,11,12 & 24 and SOC at 3%.
	latch due to pack going into	For 6 LED internal SOC packs, you can observe DTC 3 flashing
	Sleep Mode.	and SOC at 0%. Pack wont charge or energize its ports.
c)	SPC dropping by 1% after	For BDI packs, you would see the SOC of the pack go down by
	every power cycle.	1% per power cycle. For 6 LED internal SOC packs, you can
		observe the SOC go down by a LED light every 10 power cycles.
d)	Quantum balancing high	You could not use your pack for an extensive period of time
	voltage threshold issue.	after a topo charge, due to cell voltages being higher than
		3.55V.
e)	AC detection after charge	For BDI packs, you would see DTC 11& 12. Pack wouldn't
	issue.	energize its ports. You would then need to power cycle the
		pack for it to work properly.

Therefore, above list of batteries in the field and under warranty shall be updated to firmware release 2.0.12.11 as soon as possible to avoid potential operational impact. Please refer to the "Flux Power Software Update User Guide" posted on the Flux Power support website (<u>https://www.fluxpower.com/support</u>) for instructions on how to update the firmware on your particular model(s).

Updating Packs to firmware 2.0.12.11 will correct known issues as well as previous fixes that have been deployed in the past.

The overall estimated time to complete this process differs per model and typically takes between 10 minutes and up to 30 minutes per battery, once the process is understood.

Flux Power Contact Details

Flux Power Inc. Address: 2685 South Melrose Drive, Vista, CA 92081 Tel: 877-358-9487 Option 1 Email: <u>Support@fluxpower.com</u> Web: <u>www.fluxpower.com</u>

Copyright © 2018 Flux Power, Inc. All rights reserved. Flux Power, the Flux Power Logo, and Flux Power LiFT Pack are registered trademarks or trademarks of Flux Power, Inc. All other brands and product names are trademarks or registered trademarks of their respective owners. This information is intended for the use of Flux Power customers only. Any other use without the express written consent of Flux Power, Inc. is strictly prohibited.

11/25/20, 990845v1.0

